

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	141	hysteresis and (delay\$1locked\$1loop or (delay near loop))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/09 09:20			
2	BRS	L5	2386	331/25.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/09 09:16			
3	BRS	L6	4137	delay near lock\$3 near loop	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/09 09:16			
4	BRS	L7	1	L5 and L6 and L1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/09 09:16			
5	BRS	L8	14	hysteresis same (delay\$1locked\$1loop or (delay near loop))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/09 09:42			
6	BRS	L9	102	hysteresis same (phase near detector)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/09 09:42			

	Type	Hits	Search Text	DBs	Time Stamp	Comments
1	BRS	1576	331/1a.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/08 12:38	
2	BRS	2384	331/25.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/08 12:39	
3	BRS	1419	331/1r.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/08 12:40	
4	BRS	1853	331/17.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/08 12:40	
5	BRS	4	S1 and S2 and S3 and S4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/08 12:44	
6	BRS	255	S1 and S2 and S4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/08 12:45	
7	BRS	4129	delay near lock\$3 near loop	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/08 12:47	
8	BRS	3	S6 and S7	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/08 12:50	
9	BRS	44	S2 and S7	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2004/12/09 09:15	